Unobtainium Supply Co When it's NLA, who do you call?



Product & Services Catalog

Effective: 20-DEC-2023

Unobtainium Supply Co. When it's NLA, Who do you call?

Product & Services Catalog

Table of Contents

Table of Contents	2
Ordering & Contact Information	3
NEW PRODUCTS:	
Coachwork and Interior Trim Products	
K-Jetronic (CIS) Products:	
3x8 TARGA LATCH Parts & Restoration Service:	33
Column Switch Parts:	
Column Switch Services:	38
NOTES:	49

Ordering & Contact Information

ORDERING:

Please send the following:

- a list of the items being ordered,
- the address they will be shipped to,
- Whether or not you would like us to send you a PayPal invoice for easy payment.

To the eMAIL or mail address shown below.

NOTE: We reply to several hundred e-mail inquiries every week. We can't always remember every previous e-mail correspondence we have had when you call us up or mail us an order. During order placement you MUST reference any special options, requirements, etc we agreed upon, either verbally or in writing, or we cannot guarantee that your special requirements will be included on the order. **Catalog prices do not include shipping.**

TERMS:

Payment is due upon receipt of order.

PAYMENT OPTIONS:

- 1. I can send you a PayPal invoice. The 3.2%(4.2% international) PayPal surcharge will be added to the invoice total).
- 2. Electronic images of a personal, business or bank check **drawn on a US Bank & payable in \$US** to Unobtainium Supply Co.: If you have a scanner, send 200dpi to 300dpi .JPG images (please NOT PDF) of the front & back via separate (for security) eMAILs.

I will add an endorsement to the back image & deposit the check electronically. Please hold onto the check until your bank shows that it has been paid, and then destroy it.

- 3. Mail a personal, business or bank check **payable in \$US** to:
 - i. Unobtainium Supply Co. 523 Longley Rd. Groton, MA USA 01450
- **4.** Heck, we'll even take \$ US cash, but **sorry, we're not yet set up for credit cards.**

International bank transfers are also undesirable as our US bank charges a \$50 USD handling fee!

SHIPPING:

Buyer pays shipping, & insurance costs from Groton, MA, Zip 01450, USA NOTE: CATALOG PRICES DO NOT INCLUDE SHIPPING.

When shipping to **Unobtainium Supply Co.** please instruct shipping company or write on the box: "Signature not needed. Please place inside large grey plastic bin by garage."

CUSTOMS: When sending items such as column switches for restoration, list them as customs category OTHER & use the description "Antique Auto Parts to be repaired and returned". This usually will avoid customs duties.

TIPS for PACKING COLUMN SWITCHES:

We suggest wrapping the main body with bubble wrap, then inserting sections of ~2" mailing tube over the stalks. The mailing tube should be about 1" longer than the stalk it's protecting. Tape the mailing tube to the bubble wrap, then wrap everything with more bubble wrap, or pack with inflated plastic packing. You can leave the housing around the switch. However, if the housing is metal, make certain it cannot shift & break a stalk when the package is tossed around.

We DO NOT recommend using packing 'popcorn' I've had switches arrive where the popcorn had shifted & allowed a stalk to get broken off.

Of course, mark the box **FRAGILE**, it might help but they'll probably toss it anyway(sigh). If the switch has a stalk broken off, please make sure that the box is large enough to hold the restored switch for return shipping. I recommend **USPS Priority Mail**, they don't ship large heavy things so unlikely to be crushed.

Ordering & Contact Information (cont'd):

CONTACT/ORDERING INFORMATION

Business Hours: Monday thru Friday 9:00 AM - 5:00 PM Eastern Time

eMAIL/PayPal: Orders@UnobtainiumSupply.com

Phone: 978-448-2110, Cell: 978-337-2294

MAIL/Shipping Address*:

Unobtainium Supply Co. 523 Longley Rd. Groton, MA USA 01450-1026

Web Page: http://www.UnobtainiumSupply.com/

Facebook: https://www.facebook.com/Unobtainium-Supply-Co-322805308326/
New Product Announcements, Items of timely interest, direct communications

ANNUAL HOLIDAY SHUT-DOWN:

We shut down manufacturing & restoration services starting the week before Thanksgiving thru New Years, but will ship parts that are 'on the shelf'.

This shutdown is because:

- Holiday events & shopping take up so much time that we just can not make predictable turn-around promises.
- We have found that there are very few new orders during this period.
- We use this time to work off our backlog, develop new products & replace worn out molds.

However, if you really have an emergency, contact us, we'll help if it is possible.

Unobtainium Supply Co. When it's NLA, Who do you call?

NEW PRODUCTS:

	<u>Part#</u>	<u>Description</u>	Used On	Shipping Weight	<u>Price</u>
00	60164001	Bezel, Ignition Lock Surround	All variants: 308 & 328	1 oz	\$49.77 These are made to order, usually ship 3-5 business days after payment is received.
FERRARI F 106 AB - (308 GTB) + D G M 15346 OM + MOTORE F 106 A 021 ABTOTELABO - CHASSIS F 106 AB *	F106AB VIN PLATE	UNSCRATCHABLE 308GTB VIN plate Very exact reproduction	Carb'd 308GTB	1 oz	\$97.00

	<u>Part#</u>	<u>Description</u>	<u>Used On</u>	Shipping Weight	<u>Price</u>
AUTOVETTURA FERRARI F 106 AB (FERRARI308GTB) E 2 10R-75030 E 11 11R-0174 17R-027 E 11 12R-0150 18R-015 E 2 E 11 14R-75.027 25R-009	AUTTOVETTUR A EC GTB	UNSCRATCHABLE 308GTB F106AB AUTOVETTURA EURO compliance plate. very exact reproduction	Early Euro 308GTB	1 oz	\$97
	ADJCVR- UPRSM	Seat Adjuster Upper Cover, smooth finish (for LH #40124604 & RH #40124703 adjusters)	308, 512BB	2 oz	\$97.00 These are made to order, usually ship 3-5 business days after payment is received.
	129620	Cover, Coil Wire Protective	208 Turbo, 328, 412 Mondial3.2 Testarossa	2 oz	\$49.95 These are made to order, usually ship 3-5 business days after payment is received.

Coachwork and Interior Trim Products

<u>lmage</u>	Part#	<u>Description</u>	Used On	Shipping Weight	<u>Price</u>
		Bezel, Lever Satin Black, Unbreakable Al (See our matching Unscratchable Label Plate Sets)	308GT4, others	2 oz 8 oz/4	\$129.00/bezel \$516.00/4 bezels
	60044302-BEZL	Bezel, Lever Chrome Unbreakable Al (See our matching Unscratchable Label Plate Sets)	308GTS/B Can be used on: 400, Daytona, others	2 oz 8 oz/4	\$129.00/bezel \$516.00/4 bezels
	60548100-BEZL	Bezel, Lever Early Chrome Unbreakable Al, w/groove on tab, 1 hole w/rounded ends (See our matching Unscratchable Label Plate Sets)	206/246, 365 GTB4, Boxer, others	2 oz 8 oz/4	\$75.69/bezel NOTE: Supply limited
	60073905-FLEX	Boot Prop Flex Joint	308	3 oz	\$ 97.00

<u>lmage</u>	Part#	<u>Description</u>	<u>Used On</u>	Shipping Weight	<u>Price</u>
	61652700-HLDR	Bulb socket holder, taillight	Testarossa	2 oz	\$47.00
4	60551400	Bumper, Rubber Mid Louver, Newer – 1 pair	1981 328 308 GTS & GTB	2 oz	\$47.00
44	20106001 Superceded from 60551400	Bumper, Rubber GTS Louver, corner – 1 pair	all 3x8 GTS, also Mid louver GTS up to 1981	2 oz	\$47.00
	BELTBRKT-A	Cover, Seat Belt Bracket Style A Qty 1 (Snaps onto the metal bracket)	308 Carb'd others	1 oz	\$ 47.00

<u>lmage</u>	Part#	<u>Description</u>	Used On	Shipping Weight	<u>Price</u>
	BELTBRKT-B	Cover, Seat Belt Bracket Style B Qty1 (Curved front)	308 Carb'd others	1 oz	\$ 47.00
	BELTBRKT-C	Cover, Seat Belt Bracket Style C Qty 1 (Mounts by snapping around the washer under the bolt head)	308 2V injected others	1 oz	\$ 47.00
	20107801-CYL	Cover, Seat Belt Bracket Dino (Cylinder inside snaps onto bolt head)	Dinos, others	1 oz	\$ 47.00
	20107801-KLIP	Cover, Seat Belt Bracket Dino (KLIPPAN molded on top.) Specify: Symmetric or Asymmetric mounting, sold as pairs)	Dinos, others	2 oz	\$ 94.00

<u>Image</u>	Part#	<u>Description</u>	Used On	Shipping Weight	<u>Price</u>
	113047- CRYSTAL	Crystal, flat optical glass 46.84mm diameter w/notch for clock stem	Dinos, 308, 328, others	1 oz	\$ 73.11
	116956- CRYSTAL	Crystal, flat optical glass 46.84mm dia. Smallinstrument (temp, pressure) NOTE: Optical glass crystals for larger instruments is custom orderable, contact us for a quote.	Dinos, 308, 328, others	1 oz	\$ 53.73
		Emblem, '308' Black Chrome Plastic	308	3 oz	\$ 75.00
		Emblem,308 Black Plastic	308	2 oz	\$ 55.00
	60623200	Antenna Gasket, Bosch Autojet II & others	Most '70s & '80s Ferraris	1 oz	\$ 47.00

<u>lmage</u>	Part#	<u>Description</u>	<u>Used On</u>	Shipping Weight	<u>Price</u>
	60623100	Antenna Base, Bosch Autojet II	Most '70s & '80s Ferraris	1 oz	\$47.00
	50371103 - SET	Bumper End Trim, set of 4 pcs & 4 plastic friendly rivets.	Boxer		\$127/set of 4
	61455400	Bezel, 308 Door Handle - 1 pair	1980 & newer 308s, 288 GTO	1 oz	\$47.00
	61111300- KNOB	Knob, Mirror Switch	308 QV	1 oz	\$ 40.00

<u>lmage</u>	Part#	<u>Description</u>	<u>Used On</u>	Shipping Weight	<u>Price</u>
	60086105- HSNG	Latch Housing, Boot (engine cover) w/hole for cable.	308/328	2 oz	\$ 97.00
Jolland Control of the Control of th	61756700- HSNG	Latch Housing, Bonnet (spare tire cover) w/raised boss for cable.	308/328/ Testarossa/ 512TR	2 oz	\$ 97.00
	50036508- HSNG	Latch Housing, Bonnet & Boot	308GT4, Dino 206 GT and 246 L-series, 512 BB & BBI, 288 GTO	4 oz	\$ 97.00

<u>lmage</u>	Part#	<u>Description</u>	<u>Used On</u>	Shipping Weight	<u>Price</u>
D D D E F F F	LVRPLT-INJV8	Lever Label Plate Set, Unscratchable, Injected V8 Cars (2-TEMP w/red & blue bars, 2-DEF w/windshield icon)	308 QV, 308 GTSi/GTBi, others	1 oz	\$95.00
D C C H O K E	LVRPLT- CARBD	Lever Label Plate Set, Unscratchable, Carb'd Cars (1-TEMP w/red & blue bars, 2-DEF,1-CHOKE)	Carb'd 308s, others	1 oz	\$95.00
D D C C H C K E	LVRPLTDINO	Lever Label Plate Set, Unscratchable, Dinos (1- TEMP w/red & blue dots, 2- DEF,1-CHOKE)	308 GT4, 246 Dino	1 oz	\$95.00

<u>lmage</u>	Part#	<u>Description</u>	<u>Used On</u>	Shipping Weight	<u>Price</u>
	LVRPLTDINO- EARLY	Lever Label Plate Set, Unscratchable, Euro Dinos w/2 heaters (1- w/red & blue dots for temp, 2-DEF,1- w/red & blue dots for choke)	246 Dino	1 oz	\$95.00
	LVRPLTDINO- DWNARROW	Lever Label Plate Set, Unscratchable, Euro Dinos w/ 1 heater (1- w/O & down arrow, 2- w/red & blue dots,1-DEF)	246 Dino	1 oz	\$95.00
	LVRPLTV12	Lever Label Plate Set, Unscratchable, Vintage V12 Cars (2-TEMP w/red & blue dots, 2-DEF)	365 GT Daytona, Later 400i others	1 oz	\$95.00

<u>lmage</u>	Part#	<u>Description</u>	<u>Used On</u>	Shipping Weight	<u>Price</u>
	LVRPLLTDAYT	Lever Label Plate Set, Unscratchable, Late Daytonas w/CHOKE on console (2-TEMP w/red & blue dots, 2-DEF, 1 CHOKE)	Late Daytona	1 oz	\$118.75
	BBLVRPLTS	Lever Label Plate Set, Unscratchable, 12 Cyl. BB Cars & Early 400i (1-TEMP w/red & blue dots, 2-DEF)	365BB, 512BB, 512BBi, Early 400i, others	1 oz	\$71.25
	62188800	MIRROR INNER COVER PLATE SX (LEFT), triangular inside door Unlike the original, this item will not become sticky, bubbly, or messy over time.	348		\$149.55

<u>lmage</u>	Part#	<u>Description</u>	<u>Used On</u>	Shipping Weight	<u>Price</u>
	62188700	MIRROR INNER COVER PLATE DX (RIGHT), triangular inside door Unlike the original, this item will not become sticky, bubbly, or messy over time.	348		\$149.55
	60991602	Mirror End Cap, Rear, rounded	US 308/328	1 oz	\$49.95
	60991600	Mirror Front Cap, Trapezoidal w/textured top	US 308/328	1 oz	\$49.95
	60991600-UNI	Mirror Front Cap, Trapezoidal w/UNIELEKTRA text top	US 308/328	1 oz	\$49.95

<u>lmage</u>	Part#	<u>Description</u>	<u>Used On</u>	Shipping Weight	<u>Price</u>
	106531-RNG	Jack Handle Ring, Hard Plastic, marked 2186752	308, Dino, others		\$47.70
0	16042940-EZ	EZBleed Thermostat Bolt + reusable fiber washer (Bleed thermostat housing w/o removing bolt!)	308, 328, Mondial8 & QV	1 oz	\$25.00
	95800014	Radiator Bleed ThumbScrew	308, 328 others	2 oz	\$35.00
	607E82142- RING	Fuel Cap Rubber Grip Ring	Dino, 308, 365, 246, Daytona & others		\$55.00

<u>lmage</u>	Part#	<u>Description</u>	<u>Used On</u>	Shipping Weight	<u>Price</u>
	106814-D	Shift Shaft Bushing, Delrin (Replaces SilentBloc)	308,328, 355,Boxers, Testarossa, Mondial8,Q V, & 3.2	2 oz	\$35.00
	SHIFTALTOOL	Shifter Alignment Tool Keeps Shifter centered in gate while working on shift linkage.			\$97.00
	106814-TOOL	Shift Shaft Bushing Removal & Insertion Tool (Delrin & SilentBloc)		2 oz	\$49.00
	95970630-US	Shift Detent Tool — Equivalent to FERRARI tool AV-630. Retains the shift rod detent balls & springs under tension to keep the shift rods aligned while changing shift seals, shift bushings or adjusting shift	308, 328, Mondial8/ QV/3.2	2 oz	\$97.00

<u>Image</u>	Part#	<u>Description</u>	Used On	Shipping Weight	<u>Price</u>
		forks.			
00	115372-Q	Shift Shaft Seal, Quattro, 1 pair – replaces square caseless seal #115372	Late Injected & QV 308, 328, later Mondial8, MondialQV & 3.2	1 oz	\$8.85
88	105558-Q	Shift Shaft Seal, Quattro/Oring combination – replaces early style 0-ring seals #105558 with a Quattro ring/O-ring pair.	Carb'd & early injected 308s & Mondial8, 308gt4	1 oz	\$12.85/2 Quattro/O- ring sets
L H FAN HAZARD WIPESPEED AFRIAL	60037504 & 60063203-AER	Unscratchable 308 Switch Plate Set, Old FHW w/AERIAL	79 & earlier 308, 308GT4	1 oz	\$98.33/set
0 L H FAN HAZARD WIPE SPEED AERIAL	60770800 & 60063203-AER	Unscratchable 308 Switch Plate Set, Newer FHW w/AERIAL	79 & newer 308 w/o heated rear window	1 oz	\$98.33/set
O I H H SS III A WIPE SPEED REAR-DEF	60770800 & 60063203-RDEF	Unscratchable 308 Switch Plate Set, Newer FHW w/REAR-DEF	308 QV w/heated rear window	1 oz	\$98.33/set
TAN /L HAZARD FAN /R CHOKE FOG	512BBSWPLTS	Unscratchable 512BB Switch Plate Set, 5 plates	512BB	1 oz	\$118.85/set

<u>lmage</u>	Part#	<u>Description</u>	<u>Used On</u>	Shipping Weight	<u>Price</u>
Ø R.FOG	60712600	Unscratchable R. FOG Switch Plate	Euro 308s w/fog light	1 oz	\$23.77/plate
8	117275-Q	Cam Seal Housing kit of 4 VITON™ Quattro Rings	4V engines from 308 & 328 thru 550	5 oz	\$ 35.49
	CAMLOCK2V	Cam Gear Locking Tool, 2V engine front & rear bank pair.	308, Mondial8	1 lb 4 oz	\$175.00/pair These are made to order, usually ship 3-5 business days after payment is received
Name of the second of the seco	CAMLOCK4V	Cam Gear Locking Tool, 4V engine front & rear bank pair.	308QV & 328	12 oz	\$175.00/pair These are made to order, usually ship 3-5 business days after payment is received.
		Lens, Dino Turn Signal	246 GT4,		\$194/pair

<u>lmage</u>	Part#	<u>Description</u>	<u>Used On</u>	Shipping Weight	<u>Price</u>
		(Sold in pairs to ensure color match)	Some Alfa models		
	SHOCK-KIT	Complete Shock adapters kit for Varishock or QA1: 1 pair of Paper Weights + 4 wheel set of Shock Adapter Bushings		2 lb 15 oz	\$533.37
88	PAPERWEIGHT S	Paper Weight, Stretched Shock Eye, avoids modifying front A-Arms when installing Varishock or QA1 – 1 pair	328 before s/n: 76626, & all 308	1 lb 8 oz /pair	\$272.00
	QA1BUSH	Shock Adapter Bushings, Varishock & QA1 - 4 wheel set	328 before s/n: 76626, & all 308	1 lb 7 oz	\$261.37

<u>lmage</u>	<u>Part#</u>	<u>Description</u>	Used On	Shipping Weight	<u>Price</u>
	2VAIP	Air Injection Plugs, 2V, M14x1.5 thread Set of 8	2V & early QV 308 & Mondial	11 oz.	\$110.00/Set of 8
	4VAIP	Air Injection Plugs, 4V, M16x1.5 thread Set of 8	Later QV 328, Mondial3.2, & 348	14 oz.	\$110.00/Set of 8
	60044401	Vent, Dash – Kidney shaped (qty 1)	208, 3x8, 288 GTO	2Oz.	\$147.00

<u>lmage</u>	<u>Part#</u>	<u>Description</u>	Used On	Shipping Weight	<u>Price</u>
	61738800	328 round dash vent complete (qty 1)	328	3 Oz	\$247.00
	61738800- REPKT	328 dash vent repair kit – 2 louvers + link	328	2 Oz	\$187.00

<u>lmage</u>	Part#	<u>Description</u>	Used On	Shipping Weight	<u>Price</u>
	61708800-CAP	Windshield Washer Reservoir Cap	328	1 oz	\$57

K-Jetronic (CIS) Products:

Part#	Description	Used On	Shipping Weight	Price
K-JETP	K-Jetronic (CIS) Plastic Fuel Line Restoration Kit. Sufficient Correct 5mm, 6mm, & 8mm polyamide line to restore the injection system.	308,Mondial (Euro & US cars with all plastic lines)	8 oz.	\$69.01
K-JETSS&P	K-Jetronic (CIS) SS & plastic Fuel Line Restoration Kit. Sufficient Correct 5mm black, 6mm black & 8mm SS braid covered polyamide line & metal sleeves to restore the complete CIS system. This kit includes everything in our Stainless Braided fuel lines kit below as well as the smaller plastic lines. It can also be used to restore the small plastic lines & retrofit the safer SS braided lines into a Euro or early US car that currently has all black plastic lines.	308,328,Mo ndial (Euro & US cars)	1lb.	\$97.39

Part#	Description	Used On	Shipping Weight	Price
K-JETSSONLY	K-Jetronic (CIS) Stainless Braided Fuel Lines Restoration Kit. Sufficient Correct 8mm SS braid covered 8mm polyamide line & sleeves to restore the following SS braided lines: - Distributor inlet line - Distributor return line - Distributor to frequency valve line - Accumulator to filter line. This kit can also be used to retrofit SS braided lines into a car with 8mm OD black plastic for these lines.	308,328,Mo ndial	1lb.	\$51.61
115532-USKIT	Kit to replace 115532 Fuel Pump to Accumulator line. Contains 2 swivel nuts, 2 sleeves & SS braid covered fuel line.	308,328,Mo ndial (Euro & US cars), 512BBi	12 oz	\$34.87
119305-USKIT	Kit to replace 119305 Fuel Pump to Accumulator line. Contains 1 banjo, 1 swivel nut, 2 sleeves & SS braid covered fuel line.	308,328,Mo ndial (Euro & US cars), 512BBi	12 oz	\$34.87
K-JETBBI	K-Jetronic (CIS) Fuel Line Restoration Kit. Sufficient Correct 5mm, 6mm, & 8mm polyamide line to	512 BBi	1lb	\$83.17

	restore the injection system.			
K-JET400	K-Jetronic (CIS) Fuel Line Restoration Kit. Sufficient Correct 5mm, 6mm, & 8mm polyamide line to restore the injection system.	400i, 412	1lb	\$77.98
K-JETP911	K-Jetronic (CIS) Plastic Fuel Line Restoration Kit. Sufficient Correct 5mm, 6mm, & 8mm polyamide line to restore the injection system	Porsche 911	8 oz.	\$126.16
K-JETSS&P911	K-Jetronic (CIS) SS & plastic Fuel Line Restoration Kit. Sufficient Correct 5mm black, 6mm black & SS braid covered 8mm polyamide line & metal sleeves to restore the complete CIS system. This kit can also be used to restore the small plastic lines & retrofit the safer SS braided lines into a car that currently has all black plastic lines.	Porsche 911with SS braid covered lines)	1lb.	\$166.87

Part#	Description	Used On	Shipping Weight	Price
K-JETTR	K-Jetronic (CIS) SS & plastic Fuel Line Restoration Kit. Sufficient Correct 6mm black & SS braid covered 8mm polyamide line & metal sleeves to restore the complete CIS system.	Testarossa & TR	1 lb	\$129.97
7001.0851	17mm long sleeve for 6mm OD SS Braid covered line		1 oz	\$3.45
7001.1052	18mm long sleeve for 9mm OD SS Braid covered line		1 oz	\$3.85
7010.0600 + 8031.0600	Conical nipple with barb for 6mm ID fuel line and M14x1.5 swivel nut,		1 oz	\$5.34
7040.90.0652	90 degree nipple with M14x1.5 swivel nut for 6mm ID I ine.		1 oz	\$13.64

7081.0600	Banjo fitting for 6mm ID line w/thru-hole for M12x1.5 banjo bolt		1 oz	\$6.28
-----------	--	--	------	--------

Part#	Description	Used On	Shipping Weight	Price
113975-TOOL	K-Jetronic (CIS) Fuel Injector Puller/Installer tool	All Ferraris with CIS	9 oz	\$97 each
K-JETBTOOL	K-Jetronic (CIS) Barb Insertion Tool One thing I've run into is that the mold is often trapping bubbles on the outside of the tool. The bubbles are cosmetic, they do not interfere with the tool's strength or operation in any way. Please ignore them As best I can tell the plastic is hardening before the bubbles can be eliminated. I'm trying to figure out a fix, but for now it's a 'feature' that makes each tool a little unique.	All Ferraris with CIS	9 0z	\$97 each

3x8 TARGA LATCH Parts & Restoration Service:

Part#	<u>Description</u>	<u>Used On</u>	Shipping Weight	<u>Price</u>
60395506-NSPR	Targa Top Latch Rubber Boot (new style w/holes for latch hinge cap screws), 1 pair	3x8 GTS	3 oz	\$97/pair
60395506-PR	Targa Top Latch Rubber Boot, 1 pair	3x8 GTS	3 oz	\$75/pair
60421500-NOSE	Targa Top Latch Rubber Nose restoration: You send the latch to us. We remove all remnants of the old rubber nose, mold a new polyurethane nose.	3x8 GTS		\$142.50/latch
60421500-L	Remove broken metal angle reinforcing piece inside of nose, make & weld a new one on. (About 50% of the latches we receive also require this)			\$95.00

Column Switch Parts:

Part#	<u>Description</u>	<u>Used On</u>	Shipping Weight	<u>Price</u>
Vitaloni 745 series switch (black body)	NEW: Ferrari 308 Column/Cluster/Headlight Switch - black body w/satin black stalks. The black stalks can be stripped & re-plated satin silver for an additional fee. Daytona/330 style petal knobs can be molded onto the wiper & turn stalk ends for an additional fee.	308 QV GTS GTB GT4 Dino Usable for Daytona & 330s, etc. by modifying the switch housing for stalk clearance.	3 lbs Special order from Europe, approx 2-3 weeks	Request current price.
116780-CONTACT	Column Switch Brass U- shaped Contact			\$42.50 2/\$75

Part#	<u>Description</u>	<u>Used On</u>	Shipping Weight	<u>Price</u>
KNOB328HDLT	Knob ¹ , 328/Mondial Headlight	328, Mondial	2 oz	\$ 47.00
KNOB328WIP	Knob ¹ , 328/Mondial Wiper	328, Mondial	2 oz	\$ 47.00
KNOBHDLTV	Knob ¹ , 308 Headlight, for stalk with V shaped contacts inside the knob.	308 QV, later GTSi & GTBi some 246 Dino, Daytona	2 oz	\$ 47.00
KNOBHDWRP	Knob ¹ , Headlight – for stalks with contacts that wrap around the switch body inside the stalk.	Early 308s, 308GT4, 246 Dino, Daytona	2 oz	\$ 47.00

¹You should know that while the icon grooves will be impressed into the new knob, they will not be filled with white.

We have not come up with a cost effective way of marking the Icons. It is doable, but just takes several hours of work with a fine artist's brush, white lacquer, and usually some sanding & polishing.

<u>Part#</u>	<u>Description</u>	<u>Used On</u>	Shipping Weight	<u>Price</u>
KNOBRETRING	Mold a new twist knob retaining ring around stalk	Headlight,. Or Wiper w/twist knob		\$75.00
TABTCREP	Turn Cancel Post Repair: Machine broken tab area, Design & 3D print a custom retaining tab.	328, 308 Mondial, some 246 Dino, Daytona		\$197.00
RINGTCANCL	Ring, Turn cancel black body switch w/o brass horn commutator ring	246 Dino, others	2 oz	\$ 47.00
	Transfer brass horn commutator ring & horn contact wire from your old turn cancel ring			\$75.00
	Make a new brass horn commutator ring & horn contact wire & install on turn cancel ring			\$225.00

<u>Part#</u>	<u>Description</u>	<u>Used On</u>	Shipping Weight	<u>Price</u>
STALK-HDLT	Stalk, Headlight w/twist knob ¹	328, 308 QV GTS GTB GT4, Mondial, Dino & Daytona	6 oz	NEW Reproduction: \$585.00 Remanufactured may be available, call for availability & price.
STALK- NOTWISTBLK	Stalk, Turn Signal or Wiper w/o twist knob ¹ (Black shaft)	308/328/TR/ 348	3 oz	\$317.00
STALK- NOTWIST	Stalk, Turn Signal or Wiper w/o twist knob ¹ (Satin Metal shaft)	365, 246 Dino, Early 308s, 308GT4, others	3 oz	\$367.00
STALK- WIPSWITCH	Stalk, Wiper w/Twist Kno1b (Black shaft)	328 & Mondial	4 oz	\$585.00(call for availability)
STALK-PETAL	Stalk, Headlight, turn, or wiper w/petal knob	330 GTC, Dino, others w/chrome plated or satin metal stalks	6 oz	\$525 (Chrome new reproduction) \$485.00 (satin silver new reproduction) \$350.00 (used in good condition – call for availability)

¹You should know that while the icon grooves will be impressed into the new knob, they will not be filled with white.

We have not come up with a cost effective way of marking the Icons. It is doable, but just takes several hours of work with a fine artist's brush, white lacquer, and usually some sanding & polishing.

Part#	<u>Description</u>	<u>Used On</u>	Shipping Weight	<u>Price</u>
REINFBAND	Reinforce Pivot Post or top plate mounting boss-machine & custom fit a reinforcing band around the boss.	Any column switch		\$187.50

Column Switch Services:

Part#	<u>Description</u>	<u>Used On</u>	Shipping Weight	<u>Price</u>
Column Switch Stalk Svc Vitaloni 745 series switch (black body):	Stalk Repair Service (Mold 1 new knob ¹ or pivot end on a stalk) You remove/install stalk.	308, 328, 348 Wiper, 308,328, 348, 400i, 412 or Mondial Turn Signal	6 oz	\$195.00
		308,328, or Mondial Headlight,. 328, 400i, 412 or Mondial Wiper w/twist knob		\$245.00
	We Remove & reinstall stalk			Add \$75.00
Column Switch Stalk Svc – 330 GTC, 275, 365 GT4, Daytona,	Stalk Repair Service (Mold 1 new knob ¹ or pivot end on a stalk) You remove/install stalk.	Wiper/Turn Signal or Headlight w/petal knob	6 oz	\$245.00
246 Dino(early), others w/similar Vitaloni 745 white body switch		Headlight w/Twist Knob		\$295.00
Switch	We Remove & reinstall stalk			Add \$75.00
	Make & Silver braze new headlight pivot end internal metal reinforcement (refinishing service also			Add \$75.00

We have not come up with a cost effective way of marking the Icons. It is doable, but just takes several hours of work with a fine artist's brush, white lacquer, and usually some sanding & polishing.

Part#	<u>Description</u>	<u>Used On</u>	Shipping Weight	<u>Price</u>
348 & TR series Column Switch Stalk Svc	Stalk Repair Service (Mold 1 new knob or pivot end on a stalk) You remove/install stalk.	348, TR series, MondialT Wiper, or Turn Signal	6 oz	\$225
348 & TR series Screwed Turn or Wiper signal mechanism service	: Remove screws, disassemble, mold new pivot end onto stalk, clean & detarnish contacts, reassemble.	Testarossa, TR, 512, 348, MondialT, others.		\$300.00
348 & TR series Riveted Turn or Wiper signal mechanism service:	Remove rivets, disassemble, mold new pivot end onto stalk, clean & detarnish contacts, reassemble w/custom machined plastic friendly screws	и		\$375.00

required) ¹You should know that while the icon grooves will be impressed into the new knob, they will not be filled with white.

Vitaloni 745 switch Headlight or Wiper twist switch mechanism	Mold new contact holder body onto stalk, transfer contacts to body, and solder wires to contacts.	All Vitaloni 745 switch variants	\$225.00
repair	If this is the only stalk end		\$75.00
	being replaced as part of a full switch service, instead add this amount to the service price:		
	Replacement wrap style contact		Add \$75.00
	Remove & reinstall stalk		Add \$75.00

Part#	<u>Description</u>	<u>Used On</u>	Shipping Weight	<u>Price</u>
Column Switch Stalk Strip & Refinishing Service	Strip the old black or silver finish off of a stalk. Remove any corrosion & treat to prevent it recurring. Silver stalks can be electroplated with satin zinc & clear coated, or refinished with satin black. Black stalks refinished satin black.	Any black or satin silver column switch stalk		\$95.00/stalk
	If the stalk has severe pitting/corrosion it will be sand blasted, then plated & sanded multiple times to make a best effort to fill the pitting.	Stalk with severe corrosion/ pitting		\$187/stalk
	The clearcoated satin zinc electroplating we use will most likely appear somewhat brighter than the aged silver finish on the other stalks of a switch. If you want all stalks to closely match, they all must be refinished.			

Part#	<u>Description</u>	<u>Used On</u>	Shipping Weight	<u>Price</u>
Column Switch Black Stalk Strip & color change Service	Strip the old black finish off of a stalk. Remove any corrosion & treat to prevent it recurring. Electroplate satin zinc & clearcoat The satin zinc electroplating we use will most likely appear somewhat brighter than the aged silver finish on the other stalks of a switch. If you want all stalks to closely match, they all must be refinished.	Any black column switch stalk		\$150.00/stalk

Part#	<u>Description</u>	<u>Used On</u>	<u>Shipping</u> Weight	<u>Price</u>
Column Switch Full Service & Repair 1 stalk end.	Disassemble the switch, check it over for wear & to see if any additional parts are developing cracks, clean, remove tarnish from contacts, lube contacts & moving parts, polish knobs, clean lettering & icons, then reassemble & test. If necessary mold 1 new	Vitaloni 745 series black body switch: 365 GT4, 246 Dino, 308GT4, 308, 328 others w/same style switch	3 lb	\$375.00
	knob or pivot end on a stalk. Additional repairs will be charged on a time & materials basis. (e.g.: Restore broken wiper detent post: on main body: \$125) We warrant the restored switch for 1 year.	745 white body SW: 330 GTC, 275, 365 GT4, 246 Dino(early), others.		\$445.00

Part#	<u>Description</u>	<u>Used On</u>	Shipping Weight	<u>Price</u>
Column Switch Full Svc w/new stalk	As above, but includes one complete new Wiper or Turn Signal stalk.	365 GT4, 246 Dino, 308GT4, 308, 328 others	3 lb	Add \$200 to Switch Svc.
		Headlight, or 288GTO, 328, or Mondial		Add \$345 to Switch Svc.
		Wiper		Add \$395 to Switch Svc.
		330 GTC, others w/chrome plated stalks		

Part#	<u>Description</u>	<u>Used On</u>	Shipping Weight	<u>Price</u>
TR/348 Column Switch Full Service & Headlight Stalk cam replacement	Remove headlight switch rivets, Remove Turn & wiper housing screws, disassemble clean & detarnish headlight, turn & wiper switch mechanisms, Mold a new cam onto the headlight stalk, lubricate mechanisms & Reassemble w/custom made plastic friendly screws	Testarossa, TR, 512, 348, MondialT, others.	~3 lb	\$395.00
	If riveted Turn & wiper housings, remove rivets & replace with w/custom made plastic friendly screws			Add: \$150.00
	Mold a new cam cage onto headlight stalk	u		Add \$155.00
Column Switch Stalk Svc 348 & TR series	Stalk Repair Service (Mold 1 new knob or pivot end on a stalk) You remove/install stalk.	348, TR series Wiper, or Turn Signal	6 oz	\$275
Screwed Turn or Wiper signal mechanism service	: Remove screws, disassemble, mold new pivot end onto stalk, clean & detarnish contacts, reassemble.	Testarossa, TR, 512, 348, MondialT, others.		\$345.00
Riveted Turn or Wiper signal	Remove rivets, disassemble, mold new	и		\$425.00

mechanism service:

pivot end onto stalk, clean & detarnish contacts, reassemble w/custom machined plastic friendly screws

NOTES: